


Resolving Serial Port Access Issues for the Dev Chip Board on Linux

When using the Dev Chip Board on some Linux distributions, especially on Ubuntu, you may encounter issues accessing the serial port. This usually happens due to conflicts with the brltty service or user permission restrictions. Below is an image representing when the program fails to recognize the board's ports.



This guide provides a detailed step-by-step process to diagnose and fix these issues, ensuring that your board is correctly recognized and accessible via `/dev/ttyUSB0` (or another corresponding port).

Revision #1
Created 5 March 2025 17:58:47 by Caroline
Updated 5 March 2025 17:59:27 by Caroline